



# Washington Suburban Sanitary Commission Sanitary Sewer Overflow Written Report

2728266-073-2018

MDE OFFICIAL CONTACTED: GARY ZAMERSKI

DATA CALLED IN BY: ELBE L DAVIS

DATE: 01/12/2018 AT 12:25AM

WORK ORDER(S): 2728266 2728216

EST DATE AND TIME SSO BEGAN: 01/11/2018 09:48PM DURATION: 1.53 HRS

DATE AND TIME SSO ENDED: 01/11/2018 11:20PM

SOURCE-CLEAN OUT 00402315600 WATER BODY AFFECTED-BROAD CREEK

CLOSEST STREET ADDRESS: 6112 ROSE BAY DR 20747

COUNTY/PAGE/GRID: P 5650 F04 TOWN/CITY: FORESTVILLE

CAUSE: UNKNOWN EST OVERFLOW VOLUME: 2 GAL

UPON ARRIVAL, THE WSSC CONTRACT PLUMBER FOUND EVIDENCE THE CLEANOUT AT THE PROPERTY LINE HAD OVERFLOWED TWO GALLONS. THE PLUMBER SNAKED FROM THE CLEANOUT AT THE PROPERTY LINE A TOTAL OF 45 FEET, HITTING AND RELIEVING A HARD UNKNOWN BLOCKAGE AT 15 FEET.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

WET WEATHER

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:

THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

\*

THERE IS AN UNKNOWN OBJECT STUCK AT THE BOTTOM OF THE CLEANOUT AT THE PROPERTY LINE. ONCE A WSSC CREW REMOVES THE OBJECT FROM THE CLEANOUT, A CCTV INSPECTION WILL BE PERFORMED.

\*

UPDATE 01/17/2018 - THE CCTV CREW REMOVED STICKS FROM THE BOTTOM OF THE CLEANOUT AT THE PROPERTY LINE AND PERFORMED A CCTV INSPECTION.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

LIME

VISIBLE SOLIDS REMOVED

NOTIFICATIONS MADE:

PG COUNTY HEALTH DEPT

MD DEPARTMENT OF ENVIRONMENT

PG COUNTY MUNICIPALITIES