



Washington Suburban Sanitary Commission Sanitary Sewer Overflow Written Report

2878090-074-2019

MDE OFFICIAL CONTACTED: EBONY PARRIS

DATA CALLED IN BY: BRANDON T MCCREA

DATE: 06/06/2019 AT 10:00AM

WORK ORDER(S): 2878090 2878017

EST DATE AND TIME SSO BEGAN: 06/06/2019 08:04AM DURATION: 4.43 HRS
DATE AND TIME SSO ENDED: 06/06/2019 12:30PM

SOURCE-CONTRACTOR 00401159900 WATER BODY AFFECTED-BROAD CREEK

CLOSEST STREET ADDRESS: 3504 BRINKLEY RD 20744
COUNTY/PAGE/GRID: P 5765 K02 TOWN/CITY: TEMPLE HILLS

CAUSE: DAMAGED BY OTHERS EST OVERFLOW VOLUME: 1,329 GAL
UPON ARRIVAL, THE INSPECTOR FOUND BROKEN OVERPUMPING HOSE ON BYPASS
PIPING LEAKING 5 GPM INTO HENSON CREEK. THE CONTRACTOR REPAIRED AND
REPLACED THE DAMAGED HOSE TO END THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

DRY WEATHER

NOTICEABLE ODOR

THE OVERFLOW ENTERED HENSON CREEK IN THE BROAD CREEK BASIN.

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:

THE EVENT OCCURRED FROM A BROKEN BYPASS HOSE AND THEREFORE CANNOT
BE CCTV INSPECTED.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

LIME

LIME WAS APPLIED ON AFFECTED GROUND AREAS.

NOTIFICATIONS MADE:

MD DEPARTMENT OF ENVIRONMENT
PG COUNTY MUNICIPALITIES

PG COUNTY HEALTH DEPT

ORIGINALLY REPORTED AS 3701 BRINKLEY RD

SIGNS POSTED: 2 POST DATE: 06/06/2019