



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3070521-118-2021

MDE OFFICIAL CONTACTED: AMANDA VON BANK

DATA CALLED IN BY: MARK A ALEXANDER DATE: 07/29/2021 AT 10:46PM

WORK ORDER(S): 3070521 3070510

EST DATE AND TIME SSO BEGAN: 07/29/2021 08:29PM DURATION: 2.18 HRS
DATE AND TIME SSO ENDED: 07/29/2021 10:40PM

SOURCE-OVERFLOWING MH MH15048253 WATER BODY AFFECTED-SENECA CREEK

CLOSEST STREET ADDRESS: 20432 AFTERNOON LN 20874
COUNTY/PAGE/GRID: M 4928 F10 TOWN/CITY: GERMANTOWN

CAUSE: GREASE EST OVERFLOW VOLUME: 131 GAL
UPON ARRIVAL, THE INSPECTOR FOUND MANHOLE 253M OVERFLOWING
APPROXIMATELY 1 GALLON PER MINUTE, ENTERING LAKE CHURCHILL IN THE
SENECA CREEK BASIN. THE CREW HAND-RODDED FROM MANHOLE 138U TO MANHOLE
253M AND RELIEVED GREASE AT 60 FEET, ENDING THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:
DRY WEATHER PUBLIC USE OBSERVED
PUBLIC ACCESS

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:
THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE
ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED
TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE
THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:
LIME RAKED AREA

NOTIFICATIONS MADE:
MD DEPARTMENT OF ENVIRONMENT DEP-MONTGOMERY COUNTY
MONTGOMERY CO MUNICIPALITIES

ORIGINALLY REPORTED AS 20400 BLK RW5 SUMMERSONG LANE.

SIGNS POSTED: 2 POST DATE: 07/29/2021