



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3091573-109-2021

MDE OFFICIAL CONTACTED: JAMES LYONS

DATA CALLED IN BY: SHEMIEKA MONIQUE HARDING DATE: 09/20/2021 AT 05:20PM

WORK ORDER(S): 3091573 3091550

EST DATE AND TIME SSO BEGAN: 09/20/2021 03:16PM DURATION: 6.73 HRS
DATE AND TIME SSO ENDED: 09/20/2021 10:00PM

SOURCE-REPAIR SEWER MAIN SS05139063 WATER BODY AFFECTED-ROCK CREEK

CLOSEST STREET ADDRESS: 14225 BRIARWOOD TER 20853
COUNTY/PAGE/GRID: M 5165 E06 TOWN/CITY: ROCKVILLE

CAUSE: STREAM EROSION EST OVERFLOW VOLUME: 404 GAL
UPON ARRIVAL IN THE REAR OF ADDRESS 14225 BRIARWOOD TERRACE, THE
CREW FOUND A SECTION OF SEWER PIPE MISSING AND LEAKING SEWAGE
APPROXIMATELY 1 GALLON PER MINUTE, ENTERING A NEARBY CREEK, IN THE
ROCK CREEK BASIN. A WSSC WATER CONTRACTOR SET UP OVERPUMPING FROM
MANHOLE 063U TO MANHOLE 062M, ENDING THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

DRY WEATHER DISCOLORATION
NOTICEABLE ODOR VISIBLE SOLIDS, IN STREAM

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:

A WSSC WATER CONTRACTOR WILL REPLACE THE PIPE. OVERPUMPING WILL
REMAIN IN PLACE UNTIL THE REPLACEMENT IS COMPLETE. A CCTV INSPECTION
WILL BE PERFORMED AFTER THE COMPLETION OF REPAIRS.
THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE
ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED
TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE
THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

NOTIFICATIONS MADE:

MD DEPARTMENT OF ENVIRONMENT DEP-MONTGOMERY COUNTY
MONTGOMERY CO MUNICIPALITIES

ORIGINALLY REPORTED AS 14228 BRIARWOOD TERRACE.

SIGNS POSTED: 6 POST DATE: 09/21/2021