



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3093030-109-2021

MDE OFFICIAL CONTACTED: CAROL HARRELBERGER

DATA CALLED IN BY: RAVEN O YELDER

DATE: 09/30/2021 AT 12:00PM

WORK ORDER(S): 3093030

EST DATE AND TIME SSO BEGAN: 09/30/2021 11:23AM DURATION: 6.12 HRS

DATE AND TIME SSO ENDED: 09/30/2021 05:30PM

SOURCE-REPAIR SEWER MAIN SS11032126 WATER BODY AFFECTED-BROAD CREEK

CLOSEST STREET ADDRESS: 5521 KEPPLER RD 20748

COUNTY/PAGE/GRID: P 5650 A10 TOWN/CITY: TEMPLE HILLS

CAUSE: DEFECTIVE MATERIAL EST OVERFLOW VOLUME: 367 GAL

UPON ARRIVAL, THE CREW FOUND AN OFFSET, BROKEN 8" SEWER MAIN EXPOSED IN A CREEK, LEAKING SEWAGE APPROXIMATELY 1 GALLON PER MINUTE, IN THE BROAD CREEK BASIN. A WSSC WATER CONTRACTOR SET UP OVERPUMPING FROM MANHOLE 126M TO MANHOLE 024U TO END THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

DRY WEATHER

DISCOLORATION

NOTICEABLE ODOR

VISIBLE SOLIDS, IN STREAM

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:

A WSSC WATER CONTRACTOR WILL REPAIR THE PIPE. OVERPUMPING WILL REMAIN IN PLACE UNTIL THE REPAIR IS COMPLETE. A CCTV INSPECTION WILL BE PERFORMED AFTER COMPLETION OF REPAIR.

THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

10/07/2021 UPDATE - A WSSC WATER CONTRACTOR COMPLETED A POINT REPAIR ON 10/01/2021. OVERPUMPING HAS BEEN REMOVED. A CCTV INSPECTION HAS BEEN PERFORMED.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

NOTIFICATIONS MADE:

MD DEPARTMENT OF ENVIRONMENT
PG COUNTY MUNICIPALITIES

PG COUNTY HEALTH DEPT

ORIGINALLY REPORTED AS 5410 STRATFORD LANE.

SIGNS POSTED: 7 POST DATE: 10/01/2021