



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3097481-109-2021

MDE OFFICIAL CONTACTED: EVELYN STAVROU

DATA CALLED IN BY: RAVEN O YELDER

DATE: 10/18/2021 AT 11:12AM

WORK ORDER(S): 3097481 3097457

EST DATE AND TIME SSO BEGAN: 10/18/2021 09:12AM DURATION: 7.17 HRS

DATE AND TIME SSO ENDED: 10/18/2021 04:22PM

SOURCE-REPAIR SEWER MAIN SS07071021 WATER BODY AFFECTED-CABIN JOHN

CLOSEST STREET ADDRESS: 10401 WINDSOR VIEW DR 20851

COUNTY/PAGE/GRID: M 5284 C06 TOWN/CITY: ROCKVILLE

CAUSE: STREAM EROSION EST OVERFLOW VOLUME: 12,040 GAL
UPON ARRIVAL, THE INSPECTOR FOUND A COLLAPSED 8" SEWER MAIN BETWEEN
MANHOLE 021U AND MANHOLE 020M, CAUSING SEWAGE TO LEAK DIRECTLY INTO A
TRIBUTARY TO BUCK BRANCH, IN THE CABIN JOHN BASIN. A WSSC WATER
CONTRACTOR BEGAN OVERPUMPING FROM MANHOLE 021U TO MANHOLE 020M,
ENDING THE OVERFLOW.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

DRY WEATHER DISCOLORATION
NOTICEABLE ODOR VISIBLE SOLIDS, STREAM BANK
VISIBLE SOLIDS, IN STREAM

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:

A WSSC WATER CONTRACTOR WILL MAKE REPAIRS. OVERPUMPING WILL REMAIN IN
PLACE UNTIL REPAIRS ARE COMPLETE. A CCTV INSPECTION WILL BE PERFORMED
AFTER COMPLETION OF REPAIRS.
THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE
ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED
TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE
THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

VISIBLE SOLIDS REMOVED

NOTIFICATIONS MADE:

MD DEPARTMENT OF ENVIRONMENT DEP-MONTGOMERY COUNTY
MONTGOMERY CO MUNICIPALITIES NEWSPAPER
RADIO STATIONS TELEVISION

A MEDIA ADVISORY WAS ISSUED ON 10/19/2021.

SIGNS POSTED: 12 POST DATE: 10/18/2021