



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3237748-109-2023

MDE OFFICIAL CONTACTED: EVELYN STAVROU

DATA CALLED IN BY: BRANDON T MCCREA DATE: 03/29/2023 AT 02:55PM

WORK ORDER(S): 3237748 3237747

EST DATE AND TIME SSO BEGAN: 03/29/2023 11:45AM DURATION: 6.08 HRS
DATE AND TIME SSO ENDED: 03/29/2023 05:50PM

SOURCE-REPAIR SEWER MAIN SS11036061 WATER BODY AFFECTED-BROAD CREEK

CLOSEST STREET ADDRESS: 6102 CLARIDGE RD 20607
COUNTY/PAGE/GRID: P 5766 D02 TOWN/CITY: TEMPLE HILLS

CAUSE: STREAM EROSION EST OVERFLOW VOLUME: 730 GAL
UPON ARRIVAL, THE CREW FOUND A BROKEN SEWER PIPE ENTERING A TRIBUTARY
OF BROAD CREEK. THE CONTRACTORS SET UP BYPASS OPERATIONS FROM MANHOLE
061M TO MANHOLE 003U, ENDING THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

DRY WEATHER DISCOLORATION
NOTICEABLE ODOR VISIBLE SOLIDS, STREAM BANK
VISIBLE SOLIDS, IN STREAM

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:

THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE
ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED
TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE
THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

*THE SEGMENT IS UNDER REPAIR AND THEREFORE CANNOT YET BE CCTV
INSPECTED. THE REPORT WILL BE UPDATED UPON COMPLETION OF REPAIRS AND
CCTV INSPECTION.

UPDATE 05/26/2023: A WSSC CONTRACTOR REPLACED 33' OF 8" SEWER MAIN IN THE
CREEK. A CCTV INSPECTION WAS CONDUCTED ON 05/09/2023 AND THE CONTRACTOR
REMOVED THE BYPASS PUMP SYSTEM AND RESTORED THE AREA ON 05/10/2023.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

RAKED AREA VISIBLE SOLIDS REMOVED

THE CREW SPREAD 4 BALES OF STRAW BELOW MANHOLE 004U.

NOTIFICATIONS MADE:

PG COUNTY HEALTH DEPT
MD DEPARTMENT OF ENVIRONMENT
PG COUNTY MUNICIPALITIES

SIGNS POSTED: 4 POST DATE: 03/29/2023