



WASHINGTON SUBURBAN SANITARY COMMISSION

SANITARY SEWER OVERFLOW WRITTEN REPORT

3518206-109-2025

MDE OFFICIAL CONTACTED: GREG HAWARD

DATA CALLED IN BY: BRANDON T MCCREA

DATE: 10/29/2025 AT 12:48PM

WORK ORDER(S): 3518206 3518179

EST DATE AND TIME SSO BEGAN: 10/29/2025 10:34AM DURATION: 8.93 HRS

DATE AND TIME SSO ENDED: 10/29/2025 07:30PM

SOURCE-REPAIR SEWER MAIN SS29007414 WATER BODY AFFECTED-PATUXENT RIVER

CLOSEST STREET ADDRESS: 16808

DORCHESTER PL

20772

COUNTY/PAGE/GRID: P 5653 F07

TOWN/CITY: UPPER MARLBORO

CAUSE: STREAM EROSION

EST OVERFLOW VOLUME: 268 GAL

UPON ARRIVAL, THE CREW FOUND A SLIGHT WEEPER 10' UPSTREAM FROM
MANHOLE 409U, LEAKING ONTO THE GRASSY AREA AROUND THE MANHOLE.

A WSSC MAINTENANCE CREW APPLIED A PATCH OF QUICK-CONCRETE AROUND
THE BROKEN SECTION, TO END THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

DRY WEATHER

DISCOLORATION

NOTICEABLE ODOR

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:

THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE
ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED TO
WHAT MEASURES SHOULD BE TAKEN TO REDUCE ELIMINATE THE CHANCE OF THIS LINE
OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

LIME

THE CREW SPREAD LIME IN THE GRASSY AREA AROUND THE MANHOLE.

NOTIFICATIONS MADE:

MD DEPARTMENT OF ENVIRONMENT

PG COUNTY HEALTH DEPT

PG COUNTY MUNICIPALITIES

THIS EVENT WAS ORIGINALLY REPORTED AS 16908 DORCHESTER PLACE.

SIGNS POSTED: 1 POST DATE: 10/29/2025