



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3561573-118-2026

MDE OFFICIAL CONTACTED: JORDAN RHOOMS

DATA CALLED IN BY: BRANDON T MCCREA DATE: 03/14/2026 AT 02:30PM

WORK ORDER(S): 3561573 3561571

EST DATE AND TIME SSO BEGAN: 03/14/2026 08:28AM DURATION: 2.95 HRS
DATE AND TIME SSO ENDED: 03/14/2026 11:25AM

SOURCE-OVERFLOWING MH MH07012025 WATER BODY AFFECTED-CABIN JOHN

CLOSEST STREET ADDRESS: 6859 TULIP HILL TER 20816
COUNTY/PAGE/GRID: M 5406 J06 TOWN/CITY: BETHESDA

CAUSE: GREASE EST OVERFLOW VOLUME: 177 GAL
UPON ARRIVAL, THE CREW FOUND MANHOLE 025M OVERFLOWING 1GPM ONTO THE PAVEMENT AND INTO A STORM DRAIN THAT OUTFALLS INTO CABIN JOHN CREEK. THE CREW JETTED FROM MANHOLE 010U TO 025M, A TOTAL OF 280', AND HIT AND RELIEVED GREASE AND DEBRIS AT 60', TO END THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:
DRY WEATHER PUBLIC ACCESS

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:
THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:
FLUSHED BACK INTO MANHOLE

NOTIFICATIONS MADE:
MD DEPARTMENT OF ENVIRONMENT DEP-MONTGOMERY COUNTY
MONTGOMERY CO MUNICIPALITIES

SIGNS POSTED: 1 POST DATE: 03/14/2026