



# WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3027884-073-2021

MDE OFFICIAL CONTACTED: COLLIN ZAMERSKI

DATA CALLED IN BY: BRANDON T MCCREA DATE: 01/29/2021 AT 06:20PM

WORK ORDER(S): 3027884 3027824

EST DATE AND TIME SSO BEGAN: 01/29/2021 12:20PM DURATION: 4.25 HRS  
DATE AND TIME SSO ENDED: 01/29/2021 04:35PM

SOURCE-ON-PROPERTY CLEANOUT 00481129500 WATER BODY AFFECTED-NORTHWEST BRANCH

CLOSEST STREET ADDRESS: 17710 MEETING HOUSE RD 20860  
COUNTY/PAGE/GRID: M 5050 G07 TOWN/CITY: SANDY SPRING

CAUSE: GREASE EST OVERFLOW VOLUME: 100 GAL  
UPON ARRIVAL, THE CREW FOUND EVIDENCE THE ON-PROPERTY CLEANOUT HAD RECENTLY OVERFLOWED. THE CREW JETTED FROM MANHOLE 031M TO 032M, A TOTAL OF 174 FEET, AND RELIEVED A HEAVY GREASE OBSTRUCTION AT 19 FEET, ENDING THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:  
DRY WEATHER NOTICEABLE ODOR

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:  
THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:  
LIME

NOTIFICATIONS MADE:  
DEP-MONTGOMERY COUNTY MD DEPARTMENT OF ENVIRONMENT  
MONTGOMERY CO MUNICIPALITIES

SIGNS POSTED: 1 POST DATE: 02/01/2021