

Washington Suburban Sanitary Commission Sanitary Sewer Overflow Written Report

2813450-118-2018

MDE OFFICIAL CONTACTED: JOAN HOHAN

DATA CALLED IN BY: ROBIN DESPANZA DATE: 10/07/2018 AT 12:15PM

WORK ORDER(S): 2813450 2813442

EST DATE AND TIME SSO BEGAN: 10/07/2018 08:49AM DURATION: 2.85 HRS

DATE AND TIME SSO ENDED: 10/07/2018 11:40AM

SOURCE-OVERFLOWING MH MH08008018 WATER BODY AFFECTED-NORTHEAST BRANCH

CLOSEST STREET ADDRESS: 7400 HENDRICKS DR 20784

COUNTY/PAGE/GRID: P 5410 J08 TOWN/CITY: HYATTSVILLE

CAUSE: UNKNOWN EST OVERFLOW VOLUME: 171 GAI

UPON ARRIVAL, MH018M WAS FOUND OVERFLOWING INTO A WOODED AREA AND ENTERING BRIER DITCH IN THE NORTHEAST BRANCH BASIN. THE CREW JETTED THE MAIN FROM MH018M TO MH017U, FOR 415', AND RELIEVED A HARD UNKNOWN BLOCKAGE AT 240' TO END THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

DISCOLORATION DRY WEATHER

NOTICEABLE ODOR

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:
THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE
ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE
THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT: FLUSHED BACK INTO MANHOLE LIME

LIME WAS SPREAD ON AFFECTED GROUND AREAS.

NOTIFICATIONS MADE:

PG COUNTY MUNICIPALITIES PG COUNTY HEALTH DEPT

MD DEPARTMENT OF ENVIRONMENT

SIGNS POSTED: 2 POST DATE: 10/08/2018