



Washington Suburban Sanitary Commission Sanitary Sewer Overflow Written Report

2861254-072-2019

MDE OFFICIAL CONTACTED: EVELYN STAVOG

DATA CALLED IN BY: MARK A ALEXANDER DATE: 04/11/2019 AT 02:23PM

WORK ORDER(S): 2861254 2860990

EST DATE AND TIME SSO BEGAN: 04/10/2019 06:09PM DURATION: 2.10 HRS
DATE AND TIME SSO ENDED: 04/10/2019 08:15PM

SOURCE-GRINDER PUMP 00351029400 WATER BODY AFFECTED-SENECA CREEK

CLOSEST STREET ADDRESS: 18300 CATTAIL RD 20837-8510
COUNTY/PAGE/GRID: M 5044 H06 TOWN/CITY: POOLESVILLE

CAUSE: INSTRUMENTATION/MECHANICAL FAILURE EST OVERFLOW VOLUME: 5 GAL
UPON ARRIVAL, THE INSPECTOR FOUND EVIDENCE THE WSSC GRINDER PUMP
OVERFLOWED APPROXIMATELY 5 GALLONS OF LIQUID INTO THE YARD. A WSSC
CONTRACTOR REPLACED THE GRINDER PUMP, DUE TO A BAD CAPACITOR.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

DRY WEATHER NOTICEABLE ODOR
PUBLIC ACCESS

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:
THIS OVERFLOW OCCURRED ON A GRINDER PUMP SYSTEM AND IS NOT CCTVABLE.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

LIME

NOTIFICATIONS MADE:

MD DEPARTMENT OF ENVIRONMENT DEP-MONTGOMERY COUNTY
MONTGOMERY CO MUNICIPALITIES

SIGNS POSTED: 1 POST DATE: 04/11/2019