



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3054701-073-2021

MDE OFFICIAL CONTACTED: KENDRA DUKES

DATA CALLED IN BY: KIMBERLY M B GILLIS DATE: 05/15/2021 AT 01:30AM

WORK ORDER(S): 3054701 3054681

EST DATE AND TIME SSO BEGAN: 05/14/2021 06:02PM DURATION: 12.47 HRS
DATE AND TIME SSO ENDED: 05/15/2021 06:30AM

SOURCE-SEWER SERVICE 00002089100 WATER BODY AFFECTED-BROAD CREEK

CLOSEST STREET ADDRESS: 3800-3900 REGENCY PKW 20746
COUNTY/PAGE/GRID: P 5650 E06 TOWN/CITY: SUITLAND

CAUSE: DEBRIS EST OVERFLOW VOLUME: 1,496 GAL
UPON ARRIVAL, THE INSPECTOR DISCOVERED SEWAGE ESCAPING FROM A BROKEN
6-INCH SEWER SERVICE AT A RATE OF 2 GALLONS PER MINUTE. THE SEWAGE
ENTERED A NEARBY STORM DRAIN, WHICH DISCHARGES INTO AN UNKNOWN CREEK
IN THE BROAD CREEK BASIN. A WSSC WATER CONTRACTOR SET UP BYPASS
PUMPING FROM AN ON-SITE MANHOLE TO MANHOLE #059N; ENDING THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:
DRY WEATHER NOTICEABLE ODOR
PUBLIC ACCESS

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:
A WSSC WATER CONTRACTOR WILL REPAIR THE 6-INCH SEWER SERVICE. BYPASS
PUMPING WILL REMAIN IN PLACE UNTIL REPAIRS ARE COMPLETE. A CCTV
INSPECTION WILL BE PERFORMED AFTER REPAIRS ARE COMPLETE.
THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE
ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED
TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE
THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

06/02/2021 UPDATE - A WSSC WATER CONTRACTOR COMPLETED REPAIRS ON
05/27/2021. BYPASS PUMPING HAS BEEN REMOVED. A CCTV INSPECTION HAS
BEEN PERFORMED.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

NOTIFICATIONS MADE:
MD DEPARTMENT OF ENVIRONMENT PG COUNTY HEALTH DEPT
PG COUNTY MUNICIPALITIES

ORIGINALLY REPORTED AS 3801 REGENCY PARKWAY.

SIGNS POSTED: 3 POST DATE: 05/14/2021