



# WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3065382-118-2021

MDE OFFICIAL CONTACTED: BRETT

DATA CALLED IN BY: PATRICIA A HILL DATE: 07/03/2021 AT 08:35PM

WORK ORDER(S): 3065382 3065376

EST DATE AND TIME SSO BEGAN: 07/03/2021 02:53PM DURATION: 1.90 HRS  
DATE AND TIME SSO ENDED: 07/03/2021 04:47PM

SOURCE-OVERFLOWING MH MH12015134 WATER BODY AFFECTED-LITTLE FALLS

CLOSEST STREET ADDRESS: 5701 WARWICK PL 20815  
COUNTY/PAGE/GRID: M 5407 F06 TOWN/CITY: CHEVY CHASE

CAUSE: GREASE EST OVERFLOW VOLUME: 570 GAL  
UPON THE CREW'S ARRIVAL, MANHOLE 134M WAS OVERFLOWING APPROXIMATELY  
5 GALLONS PER MINUTE. THE CREW JETTED FROM 135U TO 025U, A TOTAL OF  
418 FEET, AND RELIEVED HEAVY GREASE AT 410 FEET, ENDING THE OVERFLOW.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:  
DISCOLORATION DRY WEATHER  
NOTICEABLE ODOR

NO WATERWAY WAS DIRECTLY IMPACTED.

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:  
THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE  
ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED  
TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE  
THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:  
LIME

NOTIFICATIONS MADE:  
MD DEPARTMENT OF ENVIRONMENT MONTGOMERY CO MUNICIPALITIES  
DEP-MONTGOMERY COUNTY

ORIGINALLY REPORTED AS 5703 WARWICK PLACE.

SIGNS POSTED: 6 POST DATE: 07/03/2021 (4 SIGNS) AND 07/06/2021 (2 SIGNS)