



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3068068-073-2021

MDE OFFICIAL CONTACTED: CAROL HASELBURGER

DATA CALLED IN BY: THERESA J HAAS

DATE: 07/20/2021 AT 01:30PM

WORK ORDER(S): 3068068 3068039

EST DATE AND TIME SSO BEGAN: 07/20/2021 11:33AM DURATION: 15.95 HRS

DATE AND TIME SSO ENDED: 07/21/2021 03:30AM

SOURCE-SEWER SERVICE 00498234400 WATER BODY AFFECTED-PAINT BRANCH

CLOSEST STREET ADDRESS: 14724 BLACKBURN RD 20866

COUNTY/PAGE/GRID: M 5168 A05 TOWN/CITY: BURTONSVILLE

CAUSE: DEFECTIVE MATERIAL EST OVERFLOW VOLUME: 957 GAL

UPON ARRIVAL, THE INSPECTOR FOUND SEWAGE COMING OUT OF THE GROUND BEHIND 14716 BLACKBURN ROAD. UPON FURTHER INVESTIGATION, IT WAS DETERMINED THE SEWAGE WAS COMING FROM A BROKEN SEWER SERVICE AT 14724 BLACKBURN ROAD. A WSSC WATER CONTRACTOR REPAIRED THE SEWER SERVICE, ENDING THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

DRY WEATHER

NOTICEABLE ODOR

PUBLIC ACCESS

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:

A WSSC WATER CONTRACTOR REPLACED AN 8"X4" TEE AND 10 FEET OF THE 4-INCH SEWER SERVICE PIPE. A CCTV INSPECTION HAS BEEN PERFORMED.

THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

LIME

NOTIFICATIONS MADE:

MD DEPARTMENT OF ENVIRONMENT

DEP-MONTGOMERY COUNTY

MONTGOMERY CO MUNICIPALITIES

ORIGINALLY REPORTED AS 14716 BLACKBURN ROAD.

SIGNS POSTED: 4 POST DATE: 07/20/2021