

## WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3117836-118-2022

MDE OFFICIAL CONTACTED: EVELYN STAVROU

DATA CALLED IN BY: SHEMIEKA MONIQUE HARDING DATE: 01/19/2022 AT 01:40PM

WORK ORDER(S): 3117836 3117809

EST DATE AND TIME SSO BEGAN: 01/19/2022 11:49AM DURATION: 1.18 HRS

DATE AND TIME SSO ENDED: 01/19/2022 01:00PM

SOURCE-OVERFLOWING MH MH12015134 WATER BODY AFFECTED-LITTLE FALLS

CLOSEST STREET ADDRESS: 5701 WARWICK PL 20815

COUNTY/PAGE/GRID: M 5407 F06 TOWN/CITY: CHEVY CHASE

CAUSE: GREASE EST OVERFLOW VOLUME: 354 GAL UPON ARRIVAL THE CREW FOUND MANHOLE 134M OVERFLOWING APPROXIMATELY 5GPM INTO A NEARBY CREEK; IN THE LITTLE FALLS BASIN. THE CREW JETTED

FROM MANHOLE 135U THRU 134M TO 025U A TOTAL OF 418FT, AND RELIEVED A

HEAVY GREASE BLOCKAGE AT 418FT; ENDING THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

NOTICEABLE ODOR PUBLIC ACCESS

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:

THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE

ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUC
TED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE

THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:
LIME

TWO BAGS OF LIME APPLIED AROUND AFFECTED AREA, AND YELLOW CAUTION TAPE USED TO MARK THE AREA.

NOTIFICATIONS MADE:

MD DEPARTMENT OF ENVIRONMENT DEP-MONTGOMERY COUNTY

MONTGOMERY CO MUNICIPALITIES

ORIGINALLY REPORTED AS 5703 WARWICK PL.

SIGNS POSTED: 5 POST DATE: 01/19/2022