

## WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3198093-075-2022

MDE OFFICIAL CONTACTED: REGAN MERCER

DATA CALLED IN BY: MARK A ALEXANDER DATE: 10/25/2022 AT 06:44PM

WORK ORDER(S): 3198093 3197974

EST DATE AND TIME SSO BEGAN: 10/25/2022 10:41AM DURATION: 9.32 HRS DATE AND TIME SSO ENDED: 10/25/2022 08:00PM

SOURCE-AIR REL VLV/FORCE M SS13013163 WATER BODY AFFECTED-MUDDY BRANCH

- CLOSEST STREET ADDRESS: 9900 MEDICAL CENTER DR 20850 COUNTY/PAGE/GRID: M 5163 H05 TOWN/CITY: ROCKVILLE
- CAUSE: INSTRUMENTATION/MECHANICAL FAI EST OVERFLOW VOLUME: 75 GAL UPON ARRIVAL, THE CREW FOUND A BROKEN PIECE ON A 2" GATE VALVE, WHICH CAUSED THE AIR RELIEF VALVE 163R ON THE PRESSURE SEWER TO LEAK. THE CREW REPLACED THE 2" GATE VALVE TO END THE EVENT.
- IMPACTS UPON PUBLIC HEALTH AND STATE WATERS: PUBLIC ACCESS DRY WEATHER

NO WATERWAYS WERE AFFECTED. OVERFLOW IMPACTED NEARBY GRASSY AREA.

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:

THE EVENT OCCURRED FROM AN ARV ON A PRESSURE SEWER, AND IS THEREFORE NOT CCTVABLE.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT: LIME RAKED AREA FLUSHED BACK INTO MANHOLE

SEWAGE WAS REMOVED FROM THE SITE USING A VACUUM TRUCK. SEWAGE FROM VACUUM TRUCK WAS FLUSHED BACK INTO A NEARBY GRAVITY MANHOLE.

NOTIFICATIONS MADE: MD DEPARTMENT OF ENVIRONMENT DEP MONTGOMERY CO MUNICIPALITIES

DEP-MONTGOMERY COUNTY