



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3198328-073-2022

MDE OFFICIAL CONTACTED: CHRIS SHAFFNER

DATA CALLED IN BY: ROBIN DESPANZA

DATE: 10/26/2022 AT 11:33PM

WORK ORDER(S): 3198328 3198304

EST DATE AND TIME SSO BEGAN: 10/26/2022 08:00PM DURATION: 2.00 HRS
DATE AND TIME SSO ENDED: 10/26/2022 10:00PM

SOURCE-CLEAN OUT 00060836400 WATER BODY AFFECTED-CABIN JOHN

CLOSEST STREET ADDRESS: 6408 82ND PL 20818
COUNTY/PAGE/GRID: M 5406 C05 TOWN/CITY: CABIN JOHN

CAUSE: ROOTS EST OVERFLOW VOLUME: 5 GAL
UPON ARRIVAL, THE JET CREW FOUND THE MAINLINE WAS BACKED UP. THEY
JETTED FROM MANHOLE 019U TO 045M, AND RELIEVED HEAVY ROOTS AT 4FT.
DURING THE JETTING PROCESS, THE CLEANOUT OVERFLOWED APPROXIMATELY
5 GALLONS TOTAL.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:
DRY WEATHER PUBLIC ACCESS

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:
THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE
ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED
TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE
THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:
LIME RAKED AREA
VISIBLE SOLIDS REMOVED

NOTIFICATIONS MADE:
MD DEPARTMENT OF ENVIRONMENT DEP-MONTGOMERY COUNTY
MONTGOMERY CO MUNICIPALITIES