

## WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3208245-118-2022

MDE OFFICIAL CONTACTED: PATRICK KAMMAR

DATA CALLED IN BY: PARIS S JORDAN DATE: 11/19/2022 AT 04:55PM

WORK ORDER(S): 3208245 3208237

EST DATE AND TIME SSO BEGAN: 11/19/2022 03:02PM DURATION:

DATE AND TIME SSO ENDED: 11/20/2022 12:36AM

SOURCE-OVERFLOWING MH MH17005013 WATER BODY AFFECTED-PATUXENT RIVER

CLOSEST STREET ADDRESS: 2 20707

CLOSEST STREET ADDRESS: 2 MAIN ST COUNTY/PAGE/GRID: P 5169 F04 TOWN/CITY: LAUREL

EST OVERFLOW VOLUME: CAUSE: UNKNOWN 1,723 GAL

UPON ARRIVAL, THE CREW FOUND MANHOLE 013M OVERFLOWING APPROXIMATELY

3GPM GOING INTO A NEARBY STORM DRAIN THAT ENTERS

PARKWAY BASIN. THE CREW JETTED FROM MANHOLE 029M-009U-010M TOTAL 823FT AND WERE UNABLE TO RELIEVE A HARD UNKNOWN BLOCKAGE. CONTRACTORS SET UP

OVER PUMPING TO END THE EVENT

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

DRY WEATHER DISCOLORATION NOTICEABLE ODOR PUBLIC ACCESS

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE: THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUC-TED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

THE SEGMENT IS ON BYPASS, AND THEREFORE CANNOT YET BE CCTV INSPECTED. THE REPORT WILL BE UPDATED UPON COMPLETION OF REPAIRS AND CCTV INSPECTION.

UPDATE 01/10/2023: BYPASS REMOVED 12/21/2022, AND REPAIRS AND CCTV COMPLETE 12/28/2022

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT: FLUSHED BACK INTO MANHOLE

NOTIFICATIONS MADE:

PG COUNTY MUNICIPALITIES PG COUNTY HEALTH DEPT

MD DEPARTMENT OF ENVIRONMENT

SIGNS POSTED: 3 POST DATE: 11/20/2022