



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3236993-072-2023

MDE OFFICIAL CONTACTED: KENDRA DUKE

DATA CALLED IN BY: SHEMIEKA MONIQUE HARDING DATE: 03/23/2023 AT 08:39PM

WORK ORDER(S): 3236993 3236960

EST DATE AND TIME SSO BEGAN: 03/23/2023 03:38PM DURATION: 12.37 HRS
DATE AND TIME SSO ENDED: 03/24/2023 04:00AM

SOURCE-GRINDER PUMP 00448417600 WATER BODY AFFECTED-WATTS BRANCH

CLOSEST STREET ADDRESS: 11305 GREENBRIAR PRESERVE LN 20854
COUNTY/PAGE/GRID: M 5283 C01 TOWN/CITY: POTOMAC

CAUSE: UNKNOWN EST OVERFLOW VOLUME: 148 GAL

UPON ARRIVAL, THE CREW FOUND THE GRINDER PUMP SERVICE CONNECTION
BROKEN AND LEAKING APPROXIMATELY 0.2 GPM IN THE GRASSY AREA
AROUND THE BREAK. THE CREW SHUT DOWN VALVES 122R AND 120R AND
INSTALLED A NEW COUPLING AND VALVE STEM, ENDING THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

WET WEATHER PUBLIC ACCESS

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:
THIS EVENT OCCURRED ON A GRINDER PUMP SYSTEM AND IS THEREFORE
NOT CCTV'ABLE.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:
VISIBLE SOLIDS REMOVED

THE CREW USED A VACUUM TRUCK TO REMOVE THE SEWAGE THAT POOLED IN THE
YARD AROUND THE BREAK. THE CREW WILL RETURN TO PUT DOWN
TOPSOIL, GRASS SEED, AND SPREAD GRAVEL.

NOTIFICATIONS MADE:

MD DEPARTMENT OF ENVIRONMENT DEP-MONTGOMERY COUNTY
MONTGOMERY CO MUNICIPALITIES