



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3253579-118-2023

MDE OFFICIAL CONTACTED: EVELYN STAVROU

DATA CALLED IN BY: 4581

DATE: 05/11/2023 AT 12:05PM

WORK ORDER(S): 3253579 3253550

EST DATE AND TIME SSO BEGAN: 05/11/2023 10:39AM DURATION: 3.02 HRS

DATE AND TIME SSO ENDED: 05/11/2023 01:40PM

SOURCE-OVERFLOWING MH MH07018012 WATER BODY AFFECTED-CABIN JOHN

CLOSEST STREET ADDRESS: 7100 WHITTIER BLVD 20817

COUNTY/PAGE/GRID: M 5406 K04 TOWN/CITY: BETHESDA

CAUSE: ROOTS & GREASE EST OVERFLOW VOLUME: 181 GAL

UPON ARRIVAL, THE CREW FOUND MANHOLE 012M OVERFLOWING APPROXIMATELY 1 GPM INTO THE GRASSY AREA AROUND THE MANHOLE. THE CREW JETTED FROM MANHOLE 011M TO MANHOLE 012M, A TOTAL OF 400', AND HIT AND RELIEVED GREASE AND ROOTS AT 170', TO END THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

DRY WEATHER NOTICEABLE ODOR

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:

THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

LIME

NOTIFICATIONS MADE:

MD DEPARTMENT OF ENVIRONMENT DEP-MONTGOMERY COUNTY
MONTGOMERY CO MUNICIPALITIES

THIS EVENT WAS ORIGINALLY REPORTED AS 7000 BLK RW6 WHITTIER BLVD.

SIGNS POSTED: 8 POST DATE: 05/11/2023