



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3329562-118-2024

MDE OFFICIAL CONTACTED: CHRIS S @ 11:55P

DATA CALLED IN BY: DON O DARKO

DATE: 02/15/2024 AT 11:55PM

WORK ORDER(S): 3329562 3329394

EST DATE AND TIME SSO BEGAN: 02/15/2024 05:05PM DURATION: 2.92 HRS
DATE AND TIME SSO ENDED: 02/15/2024 08:00PM

SOURCE-OVERFLOWING MH MH02045811 WATER BODY AFFECTED-PAINT BRANCH

CLOSEST STREET ADDRESS: 3843 CULLINGWORTH RD 20866
COUNTY/PAGE/GRID: M 5168 A04 TOWN/CITY: BURTONSVILLE

CAUSE: GREASE EST OVERFLOW VOLUME: 175 GAL
UPON ARRIVAL, THE CREW FOUND MANHOLE 811M OVERFLOWING 1GPM ONTO THE GRASSY AREA AROUND THE MANHOLE, AND ENTERING A TRIBUTARY OF LITTLE PAINT BRANCH. THE CREW JETTED FROM MANHOLE 812U THROUGH MANHOLE 811M, AND INTO 810M, A TOTAL OF 450', AND HIT AND RELIEVED A HEAVY GREASE BLOCKAGE AT 350', TO END THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:
DRY WEATHER NOTICEABLE ODOR
VISIBLE SOLIDS, STREAM BANK

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:
THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:
LIME RAKED AREA

THE CREW SPREAD LIME IN THE GRASSY AREA AROUND THE MANHOLE.

NOTIFICATIONS MADE:
MD DEPARTMENT OF ENVIRONMENT DEP-MONTGOMERY COUNTY
MONTGOMERY CO MUNICIPALITIES

SIGNS POSTED: 7 POST DATE: 02/15/2024