



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3338482-118-2024

MDE OFFICIAL CONTACTED: PATRICK KAMMER

DATA CALLED IN BY: ELBE L DAVIS

DATE: 03/18/2024 AT 08:04PM

WORK ORDER(S): 3338482 3338477

EST DATE AND TIME SSO BEGAN: 03/18/2024 06:56PM DURATION: 1.82 HRS

DATE AND TIME SSO ENDED: 03/18/2024 08:45PM

SOURCE-OVERFLOWING MH MH08062010 WATER BODY AFFECTED-NORTHEAST BRANCH

CLOSEST STREET ADDRESS: 10101 BACON DR 20705

COUNTY/PAGE/GRID: P 5288 D06 TOWN/CITY: BELTSVILLE

CAUSE: GREASE EST OVERFLOW VOLUME: 218 GAL

UPON ARRIVAL, THE CREW FOUND MANHOLE 010M OVERFLOWING AT 2GPM, GOING INTO A NEARBY STORM DRAIN THAT OUTFALLS INTO NORTHEAST BRANCH. THE CREW JETTED FROM MANHOLE 010M TO 009M A TOTAL OF 252', AND HIT AND RELIEVED A HEAVY GREASE BLOCKAGE AT 252'.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

DRY WEATHER PUBLIC ACCESS
PUBLIC USE OBSERVED

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:

THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

FLUSHED BACK INTO MANHOLE

NOTIFICATIONS MADE:

PG COUNTY HEALTH DEPT MD DEPARTMENT OF ENVIRONMENT
PG COUNTY MUNICIPALITIES

THIS EVENT WAS ORIGINALLY REPORTED AS 10111 BACON DRIVE.

SIGNS POSTED: 1 POST DATE: 03/18/2024