



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3506100-118-2025

MDE OFFICIAL CONTACTED: JOAN HOHMAN 178790

DATA CALLED IN BY: DON O DARKO

DATE: 09/28/2025 AT 02:50PM

WORK ORDER(S): 3506100 3506097

EST DATE AND TIME SSO BEGAN: 09/28/2025 01:16PM DURATION: 2.73 HRS
DATE AND TIME SSO ENDED: 09/28/2025 04:00PM

SOURCE-OVERFLOWING MH MH15032119 WATER BODY AFFECTED-SENECA CREEK

CLOSEST STREET ADDRESS: 10214 MILLSTREAM DR 20886
COUNTY/PAGE/GRID: M 5047 G01 TOWN/CITY: GAITHERSBURG

CAUSE: GREASE AND WIPES EST OVERFLOW VOLUME: 983 GAL
UPON ARRIVAL, THE CREW FOUND MANHOLE 119M OVERFLOWING AT APPROXIMATELY
6 GPM. THE CREW THEN JETTED FROM MANHOLE 118U TO MANHOLE 119M, A TOTAL
OF 121', AND HIT AND RELIEVED WIPES AND GREASE AT 119', TO END THE
EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:
DRY WEATHER PUBLIC ACCESS

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:
THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE
ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED
TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE
THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:
LIME

THE CREW SPREAD LIME AROUND THE AFFECTED AREA.

NOTIFICATIONS MADE:
MD DEPARTMENT OF ENVIRONMENT DEP-MONTGOMERY COUNTY
MONTGOMERY CO MUNICIPALITIES

SIGNS POSTED: 3 POST DATE: 09/28/2025