



# WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3573190-118-2026

MDE OFFICIAL CONTACTED: CHRISTIE WAGNER

DATA CALLED IN BY: MARTIA D MELVIN      DATE: 04/10/2026 AT 09:00AM

WORK ORDER(S): 3573190 3573044

EST DATE AND TIME SSO BEGAN: 04/09/2026 05:43PM      DURATION: 3.28 HRS  
DATE AND TIME SSO ENDED: 04/09/2026 09:00PM

SOURCE-OVERFLOWING MH      MH07091007      WATER BODY AFFECTED-CABIN JOHN

CLOSEST STREET ADDRESS: 6021 NEILWOOD DR      20852  
COUNTY/PAGE/GRID: M 5285 A03      TOWN/CITY: ROCKVILLE

CAUSE: GREASE AND WIPES      EST OVERFLOW VOLUME: 197 GAL  
UNPON ARRIVAL, THE CREW FOUND MANHOLE 007U OVERFLOWING ONTO THE GRASSY AREA AROUND THE MANHOLE AND INTO A TRIBUTARY OF CABIN JOHN CREEK. THE CREW THEN JETTED FROM MANHOLE 189U TO 007U A TOTAL OF 390', AND HIT AND REMOVED A BLOCKAGE OF WIPES AND GREASE AT 360', TO END THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:  
DRY WEATHER      DISCOLORATION  
NOTICEABLE ODOR      PUBLIC ACCESS  
PUBLIC USE OBSERVED

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:  
THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:  
LIME

THE CREW SPREAD LIME IN THE GRASSY AREA AROUND THE MANHOLE.

THIS EVENT WAS ORIGINALLY REPORTED AS 6100 EXECUTIVE BLVD.

NOTIFICATIONS MADE:  
MD DEPARTMENT OF ENVIRONMENT      DEP-MONTGOMERY COUNTY  
MONTGOMERY CO MUNICIPALITIES

SIGNS POSTED: 4      POST DATE: 04/10/2026