



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3594574-118-2026

MDE OFFICIAL CONTACTED: MDE (JULIO)

DATA CALLED IN BY: RASHAD S HAMEED DATE: 06/08/2026 AT 03:30PM

WORK ORDER(S): 3594574 3594529

EST DATE AND TIME SSO BEGAN: 06/08/2026 01:37PM DURATION: 2.13 HRS
DATE AND TIME SSO ENDED: 06/08/2026 03:45PM

SOURCE-OVERFLOWING MH MH07007014 WATER BODY AFFECTED-CABIN JOHN

CLOSEST STREET ADDRESS: 7808 WOODROW PL 20818
COUNTY/PAGE/GRID: M 5406 E05 TOWN/CITY: CABIN JOHN

CAUSE: ROOTS EST OVERFLOW VOLUME: 128 GAL
UPON ARRIVAL THE CREW FOUND MANHOLE 014U OVERFLOWING APPROXIMATELY
1 GPM ONTO THE GRASSY AREA AROUND THE MANHOLE. THE CREW JETTED FROM
MANHOLE 004U TO 014U A TOTAL OF 221', AND HIT AND RELIEVED ROOTS AT
25FT, TO END THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:
DRY WEATHER NOTICEABLE ODOR

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:
THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE
ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE
CONDUCTED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR
ELIMINATE THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:
LIME

THE CREW PREAD LIME IN THE GRASSY AREA AROUND THE MANHOLE.

NOTIFICATIONS MADE:
MD DEPARTMENT OF ENVIRONMENT DEP-MONTGOMERY COUNTY
MONTGOMERY CO MUNICIPALITIES

THIS EVENT WAS ORIGINALLY REPORTED AS 7810-RW WOODROW PLACE.

SIGNS POSTED: 10 POST DATE: 06/09/2026