



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

1105278 - 073 - 2026

MDE OFFICIAL CONTACTED: CHRISTY WAGNER

DATA CALLED IN BY: BRANDON MCCREA

DATE: SEPT 18, 2026 02:40 PM

WORK ORDER(S): 1105278

EST DATE AND TIME SSO BEGAN: 09/18/2026 09:36 AM

DURATION: 4.34 HRS

DATE AND TIME SSO ENDED: 09/18/2026 04:50 PM

SOURCE – FORCE MAIN 11009001F

WATER BODY AFFECTED: BROAD CREEK

CLOSEST STREET ADDRESS: 10939 MARINER DRIVE, FORT WASHINGTON, MD, 20744

COUNTY: P

TOWN/CITY: FORT WASHINGTON

CAUSE: 09 UNKNOWN

EST OVERFLOW VOLUME: 1500 GAL

UPON ARRIVAL, THE CREW FOUND LIQUID SEWAGE SURFACING AT APPROXIMATELY 3.46 GPM ONTO THE GRASSY AREA ABOVE THE 6" PRESSURE SEWER. A WSSC CONTRACTOR EXCAVATED THE BREAK AND INSTALLED A CLAMP ON THE 6" PRESSURE SEWER, TO END THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

DW - DRY WEATHER

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:

THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

LIM - LIME

THE CREW SPREAD LIME.

NOTIFICATIONS MADE:

MDE - MD DEPT ENVIRONMENT

PG COUNTY HEALTH DEPT

PG COUNTY MUNICIPALITIES

THIS EVENT WAS ORIGINALLY REORTED AS 11000 MARINER DRIVE.

SIGNS POSTED: 2

POST DATE: 09/18/2026