



Washington Suburban Sanitary Commission Collection System Discharge Written Report

9193483-074-2009

MDE OFFICIAL CONTACTED: JASON RAKER

DATA CALLED IN BY: TRACY MARUCO

DATE: 10/07/2009 AT 11:10PM

WORK ORDER(S): 9193483 9193475

EST DATE AND TIME SSO BEGAN: 10/07/2009 10:30PM DURATION: 4.50 HRS
DATE AND TIME SSO ENDED: 10/08/2009 03:00AM

SOURCE-CONTRACTOR 00310263900 WATER BODY AFFECTED-SENECA CREEK

CLOSEST STREET ADDRESS: 8504 SHADY PINE CIR 20886
COUNTY/PAGE/GRID: M 4930 B10 TOWN/CITY: GAITHERSBURG

CAUSE: DAMAGED BY OTHERS EST OVERFLOW VOLUME: 2,700 GAL
UPON ARRIVAL, THE INSPECTOR FOUND THE MAINLINE BACKED UP AND SEWAGE
BEING PUMPED FROM THE BASEMENT AT THIS ADDRESS. THE CREW JETTED FROM
MANHOLE 276M TO 277M AND REMOVED ASPHALT AT 85 FEET ENDING THE
OVERFLOW. THE CREW ALSO FOUND ASPHALT IN TWO MANHOLES.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

NOTICEABLE ODOR DISCOLORATION
DRY WEATHER PUBLIC ACCESS

THE CUSTOMER AT 8504 SHADY PINE CIRCLE DISCHARGED SEWAGE FROM THEIR
BASEMENT INTO THE YARDS AT 8504 AND 8508. THE SEWAGE ALSO RAN DOWN
THE CURB AND ENTERED A STORM DRAIN IN THE SENECA CREEK BASIN.

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:

A CONTRACTOR RECENTLY REPAVED THE SIDEWALK, ASPHALT IS BEING REMOVED
FROM TWO OTHER MANHOLES.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

GRADING OF AREA LIME

WORK ORDERS WERE GENERATED TO REMOVE THE ASPHALT FROM THE MANHOLES.

NOTIFICATIONS MADE:

DEP-MONTGOMERY COUNTY MD DEPARTMENT OF ENVIRONMENT

SIGNS POSTED: 4 POST DATE: 10/08/2009