



Washington Suburban Sanitary Commission Sanitary Sewer Overflow Written Report

2758822-118-2018

MDE OFFICIAL CONTACTED: MARK BAIL

DATA CALLED IN BY: BRANDON T MCCREA DATE: 04/21/2018 AT 04:13PM

WORK ORDER(S): 2758822 2758817

EST DATE AND TIME SSO BEGAN: 04/21/2018 03:09PM DURATION: 1.85 HRS
DATE AND TIME SSO ENDED: 04/21/2018 05:00PM

SOURCE-OVERFLOWING MH MH07066031 WATER BODY AFFECTED-CABIN JOHN

CLOSEST STREET ADDRESS: 8016 CINDY LN 20817
COUNTY/PAGE/GRID: M 5406 D01 TOWN/CITY: BETHESDA

CAUSE: ROOTS & GREASE EST OVERFLOW VOLUME: 555 GAL
UPON THE CREW'S ARRIVAL, MANHOLE 031M WAS OVERFLOWING APPROXIMATELY
5 GALLONS PER MINUTE, ENTERING A NEARBY CREEK IN THE CABIN JOHN
BASIN. THE CREW JETTED FROM MANHOLE 030M TO 031M, RELIEVING ROOTS AND
GREASE AT 180 FEET; ENDING THE OVERFLOW.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:
NOTICEABLE ODOR PUBLIC ACCESS
DRY WEATHER

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:
THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE
ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED
TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE
THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:
GRADING OF AREA LIME

NOTIFICATIONS MADE:
DEP-MONTGOMERY COUNTY MONTGOMERY CO MUNICIPALITIES
MD DEPARTMENT OF ENVIRONMENT

SIGNS POSTED: 1 POST DATE: 04/21/2018