

## Washington Suburban Sanitary Commission Sanitary Sewer Overflow Written Report

2777765-118-2018

MDE OFFICIAL CONTACTED: JOSH CAIN

DATA CALLED IN BY: MARVIN BAILEY DATE: 06/11/2018 AT 09:35PM

WORK ORDER(S): 2777765 2777763

EST DATE AND TIME SSO BEGAN: 06/11/2018 07:13PM DURATION: 1.78 HRS

DATE AND TIME SSO ENDED: 06/11/2018 09:00PM

SOURCE-OVERFLOWING MH MH12015090 & 12015191 WATER BODY AFFECTED-LITTLE FALLS

CLOSEST STREET ADDRESS: 5454 WISCONSIN AVE 20815

COUNTY/PAGE/GRID: M 5407 F06 TOWN/CITY: CHEVY CHASE

CAUSE: ROOTS & GREASE EST OVERFLOW VOLUME: UPON ARRIVAL, THE INSPECTOR FOUND MANHOLES #12015090N AND #12015191M EACH OVERFLOWING APPROXIMATELY TWO GALLONS PER MINUTE IN THE STREET, ENTERING A NEARBY STORM DRAIN IN THE LITTLE FALLS BASIN. THE CREW JETTED FROM MANHOLE #190M TO #090N, A TOTAL OF 273 FEET, HITTING AND RELIEVING HEAVY ROOTS AND GREASE AT 180 FEET; ENDING THE OVERFLOW.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

DRY WEATHER PUBLIC ACCESS

PUBLIC USE OBSERVED

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE: THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUC-TED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT: FLUSHED BACK INTO MANHOLE

NOTIFICATIONS MADE:

MD DEPARTMENT OF ENVIRONMENT MONTGOMERY CO MUNICIPALITIES

DEP-MONTGOMERY COUNTY

ORIGINALLY REPORTED AS 5425 WISCONSIN AVENUE.

SIGNS POSTED: 1 POST DATE: 06/12/2018