



Washington Suburban Sanitary Commission Sanitary Sewer Overflow Written Report

2907526-118-2019

MDE OFFICIAL CONTACTED: EBONY PARRIS

DATA CALLED IN BY: MARK A ALEXANDER DATE: 10/15/2019 AT 12:00PM

WORK ORDER(S): 2907526 2907487

EST DATE AND TIME SSO BEGAN: 10/15/2019 09:52AM DURATION: 1.92 HRS
DATE AND TIME SSO ENDED: 10/15/2019 11:47AM

SOURCE-OVERFLOWING MH MH06014107 WATER BODY AFFECTED-SLIGO CREEK

CLOSEST STREET ADDRESS: 31 HAYWARD CT 20912
COUNTY/PAGE/GRID: M 5409 A04 TOWN/CITY: TAKOMA PARK

CAUSE: DEBRIS EST OVERFLOW VOLUME: 10 GAL

UPON ARRIVAL, THE INSPECTOR FOUND EVIDENCE MANHOLE #107M HAD OVERFLOWED A TOTAL OF 10 GALLONS OF LIQUID SEWER AND HAD ENTERED A NEARBY CREEK IN THE SLIGO CREEK BASIN. THE CREW JETTED FROM MANHOLE #106M TO MANHOLE #107M A TOTAL OF 208 FEET, HITTING AND RELIEVING HEAVY DEBRIS (STONES) AT 208 FEET IN MANHOLE #107M. THE CREW USED A HOOKED SEWER POLE TO REMOVE THE STONES FROM MANHOLE #107M.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

DRY WEATHER NOTICEABLE ODOR
PUBLIC ACCESS

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:

THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

LIME

THE CREW WASHED DOWN THE STREET AND SPREAD LIME IN THE GRASSY AREA DOWNHILL FROM MANHOLE #107M.

NOTIFICATIONS MADE:

MD DEPARTMENT OF ENVIRONMENT DEP-MONTGOMERY COUNTY
MONTGOMERY CO MUNICIPALITIES

ORIGINALLY REPORTED AS 805 HAYWARD AVENUE.

SIGNS POSTED: 2 POST DATE: 10/15/2019