



WASHINGTON SUBURBAN SANITARY COMMISSION

SANITARY SEWER OVERFLOW WRITTEN REPORT

3486225-118-2025

MDE OFFICIAL CONTACTED: EVELYN STAVROU

DATA CALLED IN BY: DON O DARKO

DATE: 07/22/2025 AT 11:38AM

WORK ORDER(S): 3486225 3486199

EST DATE AND TIME SSO BEGAN: 07/22/2025 09:40AM DURATION: 3.83 HRS

DATE AND TIME SSO ENDED: 07/22/2025 01:30PM

SOURCE-OVERFLOWING MH MH07023019 WATER BODY AFFECTED-CABIN JOHN

CLOSEST STREET ADDRESS: 7110 BROXBURN DR 20817

COUNTY/PAGE/GRID: M 5406 G04 TOWN/CITY: BETHESDA

CAUSE: DEBRIS EST OVERFLOW VOLUME: 230 GAL
UPON ARRIVAL, THE CREW FOUND MANHOLE 019M OVERFLOWING AT APPROXIMATELY
1 GPM, INTO A NEARBY STORM DRAIN THAT OUTFALLS INTO CABIN JOHN BASIN.
THE CREW JETTED FROM MANHOLE 018M TO 019M, A TOTAL OF 185', AND RELIEVED
A DEBRIS BLOCKAGE OF ASPHALT AND GRAVEL FROM INSIDE THE MANHOLE, TO END
THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

DRY WEATHER DISCOLORATION
PUBLIC ACCESS

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:

THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE
ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED
TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE
THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

LIME VISIBLE SOLIDS REMOVED

THE CREW SPREAD LIME AROUND THE AFFECTED AREA AND REMOVED ALL VISIBLE
SOLIDS.

NOTIFICATIONS MADE:

MD DEPARTMENT OF ENVIRONMENT MONTGOMERY CO MUNICIPALITIES
DEP-MONTGOMERY COUNTY

SIGNS POSTED: 1 POST DATE: 07/22/2025