



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3596389-118-2026

MDE OFFICIAL CONTACTED: OLUMIDE OGUNLEYE

DATA CALLED IN BY: DON O DARKO

DATE: 06/16/2026 AT 11:21PM

WORK ORDER(S): 3596389 3596379

EST DATE AND TIME SSO BEGAN: 06/16/2026 05:23PM DURATION: 1.95 HRS

DATE AND TIME SSO ENDED: 06/16/2026 07:20PM

SOURCE-OVERFLOWING MH MH07093027 WATER BODY AFFECTED-CABIN JOHN

CLOSEST STREET ADDRESS: 11825 GAINSBOROUGH RD 20854

COUNTY/PAGE/GRID: M 5284 E03 TOWN/CITY: POTOMAC

CAUSE: ROOTS AND WIPES

EST OVERFLOW VOLUME: 351 GAL

UPON ARRIVAL, THE CREW FOUND MANHOLE 028M AND 027U OVERFLOWING A COMBINED TOTAL OF 3GPM ONTO THE GRASSY AREA AROUND THE MANHOLES AND INTO A NEARBY WATERWAY THAT OUTFALLS INTO CABIN JOHN CREEK. THE CREW JETTED FRM MANHOLE 030M TO 026U HIT AND RELIEVED ROOTS AND WIPES, TO END THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

DRY WEATHER

DISCOLORATION

NOTICEABLE ODOR

PUBLIC ACCESS

VISIBLE SOLIDS, STREAM BANK

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:

THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

LIME

VISIBLE SOLIDS REMOVED

THE CREW SPREAD LIME IN THE GRASSY AREA AROUND THE MANHOLE.

NOTIFICATIONS MADE:

MD DEPARTMENT OF ENVIRONMENT

DEP-MONTGOMERY COUNTY

SIGNS POSTED: 8 POST DATE: 06/17/2026