



Washington Suburban Sanitary Commission Collection System Discharge Written Report

9737537-118-2010

MDE OFFICIAL CONTACTED: KATHY MOHAN

DATA CALLED IN BY: KEVIN VERRETT

DATE: 06/07/2010 AT 04:00PM

WORK ORDER(S): 9737537 9736695

EST DATE AND TIME SSO BEGAN: 06/07/2010 01:57PM DURATION: 3.80 HRS

DATE AND TIME SSO ENDED: 06/07/2010 05:45PM

SOURCE-OVERFLOWING MH MH05079028 WATER BODY AFFECTED-ROCK CREEK

CLOSEST STREET ADDRESS: 11616-20 ROCKVILLE PK 20852

COUNTY/PAGE/GRID: M 5285 B03 TOWN/CITY: ROCKVILLE

CAUSE: GREASE EST OVERFLOW VOLUME: 228 GAL

UPON ARRIVAL CREW FOUND MH028N OVERFLOWING 1 GALLON PER MINUTE. CREW
JETTED FROM MH027N TO 028N AND REMOVED HEAVY GREASE, SAFETY BARREL
AND A BROKEN MANHOLE COVER WHICH STOPPED THE OVERFLOW.

<INITIAL CAUSE=13>

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

NOTICEABLE ODOR

PUBLIC ACCESS

VISIBLE SOLIDS, IN STREAM

LIGHT STREAM ENTERED THE STORM DRAIN

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:

THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE
ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED
TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE
THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

FLUSHED BACK INTO MANHOLE

THE CREW USED THE JET MACHINE TO WASH DOWN AREA.

NOTIFICATIONS MADE:

DEP-MONTGOMERY COUNTY

MD DEPARTMENT OF ENVIRONMENT