



Washington Suburban Sanitary Commission Collection System Discharge Written Report

9660291-118-2010

MDE OFFICIAL CONTACTED: JAY MILLER

DATA CALLED IN BY: KISHA L COWARD

DATE: 05/05/2010 AT 01:30AM

WORK ORDER(S): 9660291 9660234

EST DATE AND TIME SSO BEGAN: 05/04/2010 11:00PM DURATION: 3.50 HRS
DATE AND TIME SSO ENDED: 05/05/2010 02:30AM

SOURCE-OVERFLOWING MH MH07065050 WATER BODY AFFECTED-CABIN JOHN

CLOSEST STREET ADDRESS: 8600 FENWAY RD 20817
COUNTY/PAGE/GRID: M 5406 C01 TOWN/CITY: BETHESDA

CAUSE: ROOTS EST OVERFLOW VOLUME: 210 GAL
UPON ARRIVAL, THE CREW FOUND MANHOLE 050M OVERFLOWING 1 GPM. THE CREW
JETTED FROM MANHOLE 049N TO 050M A TOTAL OF 300 FEET, AND RELIEVED A
ROOTS AND PAPER STOPPAGE AT 150 FEET, ENDING THE OVERFLOW.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

DRY WEATHER

NOTICEABLE ODOR

PUBLIC ACCESS

PUBLIC USE OBSERVED

LIQUID ONLY OVERFLOWED ONTO A GRASSY AREA, NO WATERWAY IMPACTED.

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:

THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE
ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED
TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE
THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

LIME

A WORK ORDER WAS GENERATED TO SPREAD LIME IN THE MORNING.

NOTIFICATIONS MADE:

DEP-MONTGOMERY COUNTY

MD DEPARTMENT OF ENVIRONMENT

SIGNS POSTED: 3 POST DATE: 05/05/2010