



# Washington Suburban Sanitary Commission Collection System Discharge Written Report

1902121-109-2012

MDE OFFICIAL CONTACTED: BRIAN

DATA CALLED IN BY: ROBIN DESPANZA

DATE: 11/26/2012 AT 11:14PM

WORK ORDER(S): 1902121 1902022

EST DATE AND TIME SSO BEGAN: 11/26/2012 08:33PM DURATION: 2.28 HRS

DATE AND TIME SSO ENDED: 11/26/2012 10:50PM

SOURCE-REPAIR SEWER MAIN SS13007432 WATER BODY AFFECTED-MUDDY BRANCH

CLOSEST STREET ADDRESS: 10200 NOLAN DR 20850-3506

COUNTY/PAGE/GRID: M 5163 G06 TOWN/CITY: ROCKVILLE

CAUSE: DEFECTIVE MATERIAL EST OVERFLOW VOLUME: 109 GAL

UPON THE INSPECTOR'S ARRIVAL, HE FOUND 0.8 GALLONS PER MINUTE OF SEWAGE COMING UP IN A GRASSY AREA AT THE INTERSECTION OF NOLAN DRIVE AND TRAVILLAH ROAD. THE CREW CLOSED THE FLUSHING CONNECTION VALVE AT 432R, ENDING THE SPILL. THE CREW THEN EXCAVATED AND MADE THE NEEDED REPAIRS TO THE FLUSHING CONNECTION.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:

DRY WEATHER

NOTICEABLE ODOR

PUBLIC ACCESS

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:

THIS IS A PRESSURE SEWER SYSTEM AND IS NOT CCTVABLE.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

GRADING OF AREA

LIME

NOTIFICATIONS MADE:

MD DEPARTMENT OF ENVIRONMENT

DEP-MONTGOMERY COUNTY